


FIG. 1



2/8

FIG. 2A

$$F_1 > F_2$$




FIG. 2B

$$F_1 \approx F_2$$






FIG. 2C

$$F_1 < F_2$$




08807453-022797

FIG. 3A




THE PRESSURIZED FLUID WAS NOT SUPPLIED

FIG. 3B



POLISHING PRESSURE 400gf/cm²
 PRESSURE OF PRESSURIZED FLUID 200gf/cm²
 THE PRESSURIZED FLUID IS SUPPLIED ONLY TO THE FIRST CHAMBER C1


FIG. 3C



THE PRESSURIZED FLUID IS SUPPLIED ONLY TO THE THIRD CHAMBER C3

FIG. 4A FIG. 4B FIG. 4C FIG. 4D FIG. 4E

POLISHING
PRESSURE: 400gf/cm²






FIG. 5


464220" E9440880

2025 RELEASE UNDER E.O. 14176

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

6/8


FIG. 6



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

7/8

FIG. 7



0880463 0229 464220" 69440880

